



**Name – Mr. Surendra**

**Dept. – QA (Final Inspector)**

**Cell. – A351 Drum Gear**

**Defect Description ;– To Prevent the Customer complaint of defect in A351 Drum Gear Body found with  $7.1+0.05$  Track width under size by  $0.02\text{mm}$  Due to this PPG & Also Fork not answering inside track. 1nos arrested at Final inspection by:Mr.Surendra**



Track width  
 $7.1+0.05$  U/S PPG  
Not answering