


All M/C		TPM CIRCLE NO :-05	ACTIVITY	KK	QM	PM	JH	SHE	OT	DM	E&T	KAIZEN IDEA SHEET										
		TPM CIRCLE NAME: - Innovation	LOSS NO. / STEP																			
		DEPT :-QA	RESULT AREA	P	Q	A		C	D	S	M											
CELL:-	CELL NAME:- All M/C	MACHINE / STAGE :-Aii M/C					OPERATION :-															
KAIZEN THEME :-To Provide the information of gauges at every machine.		IDEA :- Make the list of gauges at every machine .																				
Problem present status :- In our machine shop not any provision for how much gauges used on that operation .		COUNTERMEASURE:- Now we have made a list of gauges with their spec and gauge number at every machine and display it at every machine.					<table border="1"> <tr> <td>BENCHMARK</td> <td>Chance of in-house</td> </tr> <tr> <td>TARGET</td> <td>No chance of in house</td> </tr> <tr> <td>KAIZEN START</td> <td>10.11.17</td> </tr> <tr> <td>TDC</td> <td>03.12.17</td> </tr> <tr> <td>KAIZEN FINISH</td> <td>12.12.17</td> </tr> </table>						BENCHMARK	Chance of in-house	TARGET	No chance of in house	KAIZEN START	10.11.17	TDC	03.12.17	KAIZEN FINISH	12.12.17
BENCHMARK	Chance of in-house																					
TARGET	No chance of in house																					
KAIZEN START	10.11.17																					
TDC	03.12.17																					
KAIZEN FINISH	12.12.17																					
<p style="text-align: center; font-size: 2em;">N A</p>							<p>TEAM MEMBERS : Abhijeet Mishra, Gaurav Verma</p>															
							<p>BENEFITS :- Knowledge of gauges and gauges no.</p>															
WHY - WHY ANALYSIS :- WHY 1:-No provision for gauges quantity and gauge number at any machine. WHY 2:- No data was at any machine.		RESULT : No any difficulty in finding how much gauges used in every machine.					<p>WHAT TO DO:-One time activity. HOW TO DO:- One time activity FREQUENCY :- Starting of shift.</p>															
ROOT CAUSE :- No Data for gauge information		<p>KAIZEN SUSTENANCE</p>																				
REGISTRATION NO. & DATE : 10.11 .17		<p>SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT</p> <table border="1"> <thead> <tr> <th>SR. NO.</th> <th>CELL</th> <th>TARGET</th> <th>RESPONSIBILITY</th> <th>STATUS</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td>----</td> <td></td> <td></td> </tr> </tbody> </table>										SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS	1		----			
SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS																		
1		----																				
REGISTERED BY :-																						
MANAGER'S SIGN :-																						