




AD  IK	TPM CIRCLE NO :-	ACTIVITY	KK	QM	PM	JH	SHE	OT	DM	E&T	KAIZEN IDEA SHEET										
	TPM CIRCLE NAME :	LOSS NO. / STEP	10									KAIZEN NO:-									
	DEPT :- Maint.	RESULT AREA	P	Q	DEF :- A/B/C	C	D	S	M												
CELL :-	CELL NAME: टेन्सओनेर	MACHINE / STAGE :- nut tapping						OPERATION :- tapping													
KAIZEN THEME : MTTR को कम करना		IDEA :-... कोन्ट्रोलपनेल को मशीन से अलग करना. .																			
WIDELY/DEEPLY :-		COUNTERMEASURE :- कंट्रोल पैनल को मशीन से अलग करके फ्लोर पेर्मोंट कर दिया.					BENCHMARK. 2 per month TARGET .0 पर month KAIZEN START 14.08.२०१७ KAIZEN FINISH 15.08.														
PROBLEM / PRESENT STATUS :-							TEAM MEMBERS :-														
Nut tapping मशीन में कण्ट्रोल पैनल मशीन के साथ माउंट था. जिससे viberaton से हिलता था. जिसकी वजह से कण्ट्रोल रिले हिल कर malfunctioning करती थी.							गुरुप्रोत सिंह, शुभम, प्रकाश														
WHY WHY ANALYSIS :-		RESULT :-					WHAT TO DO :- अप्रव्वन्नीय														
WHY : कण्ट्रोल रिले malfunctioning करती थी.		No of per month 					HOW TO DO :-														
WHY :-.. Viberation की वजह से.							FREQUENCY :-														
WHY :- कण्ट्रोल पैनल मशीन केसात mount था.		COST INCURRED FOR MAKING KAIZEN <table border="1"> <tr> <th>MATERIAL COST RS.</th> <th>LABOUR COST RS.</th> <th>TOTAL COST RS.</th> </tr> <tr> <td>5000 Rs.</td> <td>10 00/-</td> <td>6000</td> </tr> </table>					MATERIAL COST RS.	LABOUR COST RS.	TOTAL COST RS.	5000 Rs.	10 00/-	6000	SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT								
MATERIAL COST RS.	LABOUR COST RS.						TOTAL COST RS.														
5000 Rs.	10 00/-	6000																			
ROOT CAUSE .कण्ट्रोल पैनल मशीन के साथ mount		<table border="1"> <tr> <th>SR. NO.</th> <th>CELL</th> <th>TARGET</th> <th>RESPONSIBILITY</th> <th>STATUS</th> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>					SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS	5									
SR. NO.	CELL						TARGET	RESPONSIBILITY	STATUS												
5																					
REGISTRATION NO&DATE :																					
REGISTERED BY :-																					
MANAGER'S SIGN :-																					